



COMMON DIMENSIONS

SYMBOL	UNIT	MIN	MAX
E	mm	1.5	3.28
A	mm	0.36	3.43
A1	mm	4.91	3.38
A2	mm	2.74	3.65
A4	mm	0.6	3.45
A	mm	2.96	1.55
c	mm	0.65	1.43
D	mm	6.17	0.95
H1	mm	1.27	16.1
e	mm	1.27	
L	mm	1.27	
L1	mm	3.28	
$\phi P$	mm	3.43	
$\phi P3$	mm	3.38	
F3	mm	3.65	
G3	mm	3.45	
b1	mm	1.55	
b2	mm	1.43	
b3	mm	0.95	
L2	mm	16.1	